# Huawei Qualcomm – Flash Firmware by DTpro team

**Now is possible Flash Stable Firmwares in Huawei Qualcomm**

**Writing Bootloader repair File...**


**RUN Qualcomm Module**

**In Brand Option : Select Huawei and Honor Devices | e-Token Authentication**



**In Xboot Option : Select your Model**

**In Type Select : Advanced Flasher |MultiRaw**



**Connect your Device in Qualcomm Mode [EDL]**

**Now | pressing the button with the folder icon... marked in red!**



**Wait for the windows to open with to select the Firmware Folder!**

**please locate the folder with the firmware and select it! and press the Ok Button!**



**Please wait while it loads all the information into the Firmware!**

**Once the Firmware is loaded - press the Write button!**



Registered TO                                                          Menu ▼  —  X

Qualcomm Partition | Factory Partition | Android General

```
12/20/2023 3:21:07 PM - Checking Connected Devices..
12/20/2023 3:21:08 PM - Device @COM26;
12/20/2023 3:21:08 PM - Switching Phone Mode..
12/20/2023 3:21:08 PM - Comunicating..
12/20/2023 3:21:08 PM - SERIAL : 2BC81FB7
12/20/2023 3:21:08 PM - MSM_HW_ID : 001B80E1
12/20/2023 3:21:08 PM - OEM PK HASH:1 : 1816101F1302CF634F7002490E67
12/20/2023 3:21:08 PM - OEM PK HASH:2 : 34F5FCDE05A7EAFF5BA7029AA0I
12/20/2023 3:21:08 PM - SBI : 00000000
12/20/2023 3:21:08 PM - Writing Flash-Boot Loader..
12/20/2023 3:21:12 PM - Setting Config..
12/20/2023 3:21:15 PM - Memory Type : eMMC
12/20/2023 3:21:15 PM - Write Buffer : 1048576
```

Device                                           RESET EFS
Speed  115200 ▼  XBoot Hon ▼  Type  Adva ▼  EDL ▼  ☐ Frp Erase
Brand  Huawei ▼  Select Loader ...  🔥 Xiaomi Info  ❗ Boot-Info  Help

C:\Users\Mago\Desktop\repairBootloader[  📂  ‼  wipe imei  🌡 Skip Auth / UBL temp

QCOMM pro | eMMc partition | XWriter | Mi Flash

| | Partition | Size | Start Address | Filename |
|---|---|---|---|---|
| ☑ | PrimaryGPT | 240 bytes | 0x0 | gpt_main0.bin |
| ☑ | ssd | 80 bytes | 0x6 | N/A |
| ☑ | persist | 320 KB | 0x8 | N/A |
| ☑ | nvme | 50 KB | 0x8200 | N/A |
| ☑ | misc | 20 KB | 0x9480 | N/A |
| ☑ | bsp_info | 10 KB | 0x9992 | N/A |
| ☑ | reserved0 | 79.69 KB | 0x10248 | N/A |
| ☑ | oeminfo | 640 KB | 0x12288 | N/A |
| ☑ | bootfail_i... | 80 KB | 0x28672 | N/A |
| ☑ | rrecord | 80 KB | 0x30720 | N/A |

Model  Honor 50 lite [NewtonH] ▼  repair Network!  Slot Boot  [FB] Identify

⚡ Special Task  |  QR  |  QW  |  rebrand  |  ID  |  Erase  |  Write

Nokia | Samsung | Huawei | Oppo | Asus | ZTE | LG | Xiaomi | Authentication | Bootloader Unlock | AUTH | Frp erase | PM | repair DualSIM phones | IMEI repair | Mi acco

eMMC|UFS S... | www.eMMC-Software.... | Nobo... | NO Credits | No Extra Pack Activat... | QUALCOMM pro Softw... | HardWare ID : CD65B-5CF11-85297-ED...

---

**Please Wait..... | Writing Firmware**



Registered TO                                                          Menu ▼  —  X

Qualcomm Partition | Factory Partition | Android General

```
12/20/2023 3:21:08 PM - Writing Flash-Boot Loader..
12/20/2023 3:21:12 PM - Setting Config..
12/20/2023 3:21:15 PM - Memory Type : eMMC
12/20/2023 3:21:15 PM - Write Buffer : 1048576
12/20/2023 3:21:33 PM - Chip Size : 119 GB
12/20/2023 3:21:33 PM - Gpt Count : 121
12/20/2023 3:21:37 PM - Searching for Required Data..
12/20/2023 3:21:41 PM - Model Number : TFY-LX3
12/20/2023 3:21:41 PM - Build Number : TFY-L03CQ 7.1.0.186(C605E3R100P1
12/20/2023 3:21:41 PM - Android Version : 13
12/20/2023 3:21:41 PM - Preload Version : TFY-L03CQ-PRELOAD 7.1.0.1(C605
12/20/2023 3:21:41 PM - Cust Version : TFY-L03CQ-CUST 7.1.0.3(C605)
12/20/2023 3:21:41 PM - System Version : TFY-LGRP10-OVS 7.1.0.186
12/20/2023 3:21:41 PM - EMUI Version : 7.1.0.186C605E3R100P1
12/20/2023 3:21:41 PM - C_version : C605
12/20/2023 3:21:41 PM - D_version : D1
12/20/2023 3:21:41 PM - PLMN : 71606
12/20/2023 3:21:41 PM - BoardID : 8019,
12/20/2023 3:21:41 PM - Update Token : &token=5711D0FFDE673763&hma
12/20/2023 3:21:41 PM - Mode : UTF
12/20/2023 3:21:41 PM - Vendor Country : def/la
12/20/2023 3:21:41 PM - Security Flag : RT P
12/20/2023 3:21:41 PM - System Lock State : 466
12/20/2023 3:21:41 PM - Lock Status : 1
12/20/2023 3:21:41 PM - Writing.. primarygpt From : 0 To : 6;
12/20/2023 3:21:43 PM - Writing.. vbmeta_system_a From : 145920 To : 256;
12/20/2023 3:21:46 PM - Writing.. backupgpt From : NUM_DISK_SECTORS-5
```

Device                                           RESET EFS
Speed  115200 ▼  XBoot Hon ▼  Type  Adva ▼  EDL ▼  ☐ Frp Erase
Brand  Huawei ▼  Select Loader ...  🔥 Xiaomi Info  ❗ Boot-Info  Help

C:\Users\Mago\Desktop\repairBootloader[  📂  ‼  wipe imei  🌡 Skip Auth / UBL temp

QCOMM pro | eMMc partition | XWriter | Mi Flash

| | Partition | Size | Start Address | Filename |
|---|---|---|---|---|
| ☑ | PrimaryGPT | 240 bytes | 0x0 | gpt_main0.bin |
| ☑ | ssd | 80 bytes | 0x6 | N/A |
| ☑ | persist | 320 KB | 0x8 | N/A |
| ☑ | nvme | 50 KB | 0x8200 | N/A |
| ☑ | misc | 20 KB | 0x9480 | N/A |
| ☑ | bsp_info | 10 KB | 0x9992 | N/A |
| ☑ | reserved0 | 79.69 KB | 0x10248 | N/A |
| ☑ | oeminfo | 640 KB | 0x12288 | N/A |
| ☑ | bootfail_i... | 80 KB | 0x28672 | N/A |
| ☑ | rrecord | 80 KB | 0x30720 | N/A |

Model  Honor 50 lite [NewtonH] ▼  repair Network!  Slot Boot  [FB] Identify

⚡ Special Task  |  QR  |  QW  |  rebrand  |  ID  |  Erase  |  Write

Qualcomm | Vivo | Nokia | Samsung | Huawei | Oppo | Asus | ZTE | LG | Xiaomi | Authentication | Bootloader Unloc

eMMC|UFS S... | www.eMMC-Software.... | Nobo... | NO Credits | No Extra Pack Activat... | QUALCOMM pro Softw... | HardWare ID : CD65B-5CF11-85297-ED...

**Firmware Written Correctly!**



Registered TO — Menu ▼

Qualcomm Partition | Factory Partition | Android General

```
12/20/2023 3:21:54 PM - Writing.. backupgpt From : NUM_DISK_SECTORS-5
12/20/2023 3:21:56 PM - Writing.. primarygpt From : 0 To : 6;
12/20/2023 3:21:58 PM - Writing.. backupgpt From : NUM_DISK_SECTORS-5
12/20/2023 3:22:00 PM - Writing.. primarygpt From : 0 To : 6;
12/20/2023 3:22:02 PM - Writing.. backupgpt From : NUM_DISK_SECTORS-5
12/20/2023 3:22:04 PM - Writing.. primarygpt From : 0 To : 6;
12/20/2023 3:22:06 PM - Writing.. rpm_a From : 6 To : 128;
12/20/2023 3:22:08 PM - Writing.. tz_a From : 134 To : 1024;
12/20/2023 3:22:11 PM - Writing.. hyp_a From : 1158 To : 128;
12/20/2023 3:22:13 PM - Writing.. modem_a From : 1286 To : 46080;
12/20/2023 3:22:20 PM - Writing.. bluetooth_a From : 47366 To : 256;
12/20/2023 3:22:22 PM - Writing.. abl_a From : 47622 To : 1024;
12/20/2023 3:22:24 PM - Writing.. dsp_a From : 48646 To : 16384;
12/20/2023 3:22:28 PM - Writing.. keymaster_a From : 65030 To : 256;
12/20/2023 3:22:30 PM - Writing.. boot_a From : 65286 To : 24576;
12/20/2023 3:22:37 PM - Writing.. devcfg_a From : 89862 To : 256;
12/20/2023 3:22:39 PM - Writing.. qupfw_a From : 90118 To : 16;
12/20/2023 3:22:41 PM - Writing.. vbmeta_a From : 90134 To : 256;
12/20/2023 3:22:43 PM - Writing.. uefisecapp_a From : 96534 To : 512;
12/20/2023 3:22:45 PM - Writing.. featenabler_a From : 97046 To : 32;
12/20/2023 3:22:47 PM - Writing.. apdp From : 194662 To : 64;
12/20/2023 3:22:49 PM - Writing.. storsec From : 227502 To : 32;
12/20/2023 3:22:51 PM - Writing.. backupgpt From : NUM_DISK_SECTORS-5
12/20/2023 3:22:53 PM - Writing.. primarygpt From : 0 To : 6;
12/20/2023 3:22:55 PM - Writing.. backupgpt From : NUM_DISK_SECTORS-5
12/20/2023 3:22:58 PM - Setting Active Slot [1]...
12/20/2023 3:22:58 PM - Rebooting..
```

Device — RESET EFS

Speed 115200  XBoot Hon  Type Adva  EDL  ☐ Frp Erase

Brand Huawei ▼  Select Loader ...  🔥 Xiaomi Info  ❗ Boot-Info  Help

C:\Users\Mago\Desktop\repairBootloader[  📁 ‼ wipe imei  🌡 Skip Auth / UBL temp

QCOMM pro | eMMc partition | XWriter | Mi Flash

| Partition | Size | Start Address | Filename |
|---|---|---|---|
| ☑ 🔥 PrimaryGPT | 240 bytes | 0x0 | gpt_main0.bin |
| ☑ ssd | 80 bytes | 0x6 | N/A |
| ☑ persist | 320 KB | 0x8 | N/A |
| ☑ nvme | 50 KB | 0x8200 | N/A |
| ☑ misc | 20 KB | 0x9480 | N/A |
| ☑ bsp_info | 10 KB | 0x9992 | N/A |
| ☑ reserved0 | 79.69 KB | 0x10248 | N/A |
| ☑ oeminfo | 640 KB | 0x12288 | N/A |
| ☑ bootfail_i... | 80 KB | 0x28672 | N/A |
| ☑ rrecord | 80 KB | 0x30720 | N/A |

Model Honor 50 lite [NewtonH] ▼  repair Network  Slot Boot  [FB] Identify

⚡ Special Task  QR  QW  rebrand  ID  Erase  Write

IMEI repair || Mi account || Flash || Format || Dissable RSA || reset EFS || DownGrade || Factory reset

eMMC|UFS S... | www.eMMC-Software.... | Nobo... | NO Credits | No Extra Pack Activat... | QUALCOMM pro Softw... | HardWare ID : CD65B-5CF11-85297-ED...



**www.eMMC-Software.ru**
**DTPRO TEAM**