



HUAWEI

Huawei Qualcomm – Frp lock remove by DTpro team

RUN Qualcomm Module

The screenshot shows the 'RUN Qualcomm Module' software interface. The window title is 'Registered TO [Support@emmc-software.ru]'. The interface is divided into several sections:

- Navigation Tabs:** 'Qualcomm Partition', 'Factory Partition', and 'Android General'.
- Device Selection:** A dropdown menu for 'Device' and a 'RESET EFS' button.
- Configuration Options:** 'Speed' (115200), 'XBoot Autc', 'Type' (Norr), 'EDL', and 'Frp Erase' (checkbox).
- Brand and Action Buttons:** 'Brand' (Auto-Det), 'Select Loader...', 'Xiaomi Info', 'Boot-Info', and 'Help'.
- File Selection:** 'Select Raw File...', 'Select Patch...', 'wipe imei', and 'Skip Auth / UBL temp'.
- Partition Management:** Tabs for 'QCOMM pro', 'eMMC partition', 'XWriter', and 'Mi Flash'. Below is a table with columns: Partition, Size, Start Address, and Filename.
- Model and Action Buttons:** 'Model Honor 50 lite [NewtonH]', 'repair Network!', and '[FB] Identify'.
- Task Buttons:** 'Special Task', 'QR', 'QW', 'rebrand', 'ID', 'Erase', and 'Write'.

At the bottom of the window, there is a status bar with the text: 'Qualcomm | Vivo | Nokia | Samsung | Huawei | Oppo | Asus | ZTE | L'.

The taskbar at the very bottom shows: 'eMMC|UFS S...', 'www.eMMC-Software...', 'Nobo...', 'NO Credits | No Extra Pack Activat...', 'QUALCOMM pro Softw...', and 'HardWare ID : D684B-5CF59-73297-E0855'.

In Brand Option : Select Huawei and Honor Devices | e-Token Authentication

Registered TO [Support@emmc-software.ru] Menu

Qualcomm Partition Factory Partition Android General

Device [RESET EFS]

Speed 115200 XBoot Autc Type Norr EDL Frp Erase

Brand Auto-Det Select Loader ... Xiaomi Info Boot-Info Help

Select Auto-Detect
•Xiaomi Devices | e-Token Authentication
•Huawei and Honor Devices | e-Token Authentication
•Nokia HMD Smartphone Devices | Non Authentication
•Vivo Devices | Non Authentication
•Sharp Devices | Non Authentication

Model Honor 50 lite [NewtonH] repair Network Slot Boot [FB] Identify

Special Task QR QW rebrand ID Erase Write

Qualcomm | Vivo | Nokia | Samsung | Huawei | Oppo | Asus | ZTE | LG | Xiaomi | Authentication | Bootloader Unlock | AUTH | Frp erase

eMMC|UFS S... www.eMMC-Software... Nobo... NO Credits | No Extra Pack Activat... QUALCOMM pro Softw... HardWare ID : D684B-5CF59-73297-E0855

In Xboot Option : Select your Model

Registered TO [Support@emmc-software.ru] Menu

Qualcomm Partition Factory Partition Android General

Device [RESET EFS]

Speed 115200 XBoot Hon Type Norr EDL Frp Erase

Brand Huawei Select Honor X8 [TFY-??]
Honor X7 [CMA-??]
Honor X9 [ANY-??]
Honor X30 4G [ANY-??]
Huawei Nova 8i [NEN-??]
Huawei Nova 9 [NAM-??]
Huawei Nova 9 PRO [RTE-??]
Huawei HiNova9 [Hera-BD??]
Huawei HiNova9 Pro [Hebe-BD??]
Huawei Nova 9SE [JLN-??]
Honor 70 lite [RBN-??]
Honor X8a 5G [RBN-??]
Honor X8 5G [VNE-??]
Honor X30 5G [ANY-AN00]
Honor 50 pro [RNA-??]
Magic 5 lite [RMO-??]


Model Honor 50 lite [NewtonH] repair Network!.. [FB] Identify

Special Task QR QW rebrand ID Erase Write


Qualcomm | Vivo | Nokia | Samsung | Huawei | Oppo | Asus | ZTE | LG | Xiaomi | Authentication | Bootloader U

eMMC|UFS S... www.eMMC-Software... Nobo... NO Credits | No Extra Pack Activat... QUALCOMM pro Softw... HardWare ID : D684B-5CF59-73297-E0855

Connect your Device in Qualcomm Mode [EDL]



Tick "Frp Erase" Option Press Erase Button Now!....



Wait the Operation to Finish

The screenshot shows the eMMC-Software.ru application window. The title bar reads "Registered TO [Support@emmc-software.ru]". The interface is divided into several sections:

- Log:** A scrollable text area on the left contains a log of operations from 29/11/2023 08:31:16 to 08:31:48, including messages like "Sbl : 0x00000000", "Writing Flash-Boot Loader..", "Setting Config..", "Memory Type : eMMC", "Chip Size : 119.33 GB", "Gpt Count : 120", "Searching for Required Data..", "Model Number : ANY-LX3", "Build Number : ANY-L03CQ 4.2.0.165(C69E11R1P1)", "Android Version : 11", "Preload Version : ANY-L03CQ-PRELOAD 4.2.0.1(C69R1)", "Cust Version : ANY-L03CQ-CUST 4.2.0.11(C69)", "System Version : ANY-LGRP10-OVS 4.2.0.165", "EMUI Version : 4.2.0.165C69E11R1P1", "C_version : C69", "D_version : D1", "PLMN : 334020", "BoardID : 8097", "Update Token : &token=140D998BCCA9643E&hmac-", "Mode : UTF", "Vendor Country : telcel/mx", "Security Flag : RT P", "System Lock State : 466", "Lock Status : 1", "Writing Frp Block;", and "Rebooting..".
- Device Information:** A dropdown menu shows "Device" with a "RESET EFS" button. Below it, "Speed" is set to 115200, "XBoof Hon" is selected, "Type" is "Norr", "EDL" is checked, and "Frp Erase" is checked. "Brand" is "Huawei". Buttons for "Select Loader...", "Xiaomi Info", "Boot-Info", and "Help" are present.
- Actions:** Buttons for "Select Raw File...", "Select Patch..", "wipe imei", and "Skip Auth / UBL temp" are visible.
- Partition Table:** A table with columns "Partition", "Size", "Start Address", and "Filename" is shown under the "eMMC partition" tab. The table is currently empty.
- Model:** A dropdown menu shows "Model Honor 50 lite [NewtonH]". Buttons for "repair Network...", "[FB] Identify", "Special Task", "QR", "QW", "rebrand", "ID", "Erase", and "Write" are located at the bottom.

The status bar at the bottom of the application window displays: "Qualcomm | Vivo | Nokia | Samsung | Huawei | Oppo | Asus | ZTE | LG | Xiaomi | Authentication | Box". The taskbar at the very bottom shows: "eMMC[UFS S... | www.eMMC-Software... | Nobo... | NO Credits | No Extra Pack Activat... | QUALCOMM pro Softw... | HardWare ID : D684B-5CF59-73297-E0855".

Note :

Device requires factory reset from recovery, after removing Frp lock.



www.eMMC-Software.ru

DTPRO TEAM